


DEPARTMENT OF ECOLOGY State of Washington		Cleanup Site Details				3/14/2016		
CLALLAM COUNTY								
SITE ID: BEAVER MILL		Cleanup Site ID: 1489				FS ID: 9356558		
Alternate Name(s): BEAVER MILL								
LOCATION:		WRIA: 20	Lat/Long: 48.069 -124.261		View Vicinity Map			
Address: 200673 HWY 101 BEAVER 98305		Township 30N	Range 12W	Section 29	Legislative District: 24 Congressional District: 6			
STATUS: No Further Action		Rank:		View Site Web Page		View Site Documents		
Responsible Unit: Southwest		Site Manager: Kourehdar, Mohsen		Statute: MTCA				
Is Brownfield?		Has Environmental Covenant?		Is PSI Site?				
NFA Received? Yes		NFA Date: 9/8/2003		NFA Reason: NFA-Voluntary Cleanup Program Review				
ASSOCIATED CLEANUP UNIT(S)								
culID	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID		
3231	BEAVER MILL	Upland	Voluntary Cleanup Program	No Further Action Required				
SITE ACTIVITIES:								
Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Site Status Changed to NFA			9/8/2003			
VcpProject	SW0461	VCP Application	Completed	1/13/2003				Kourehdar, Mohsen
VcpProject	SW0461	VCP Opinion on Remedial Investigation	Completed	1/13/2003	9/8/2003			Kourehdar, Mohsen
VcpProject	SW0461	VCP Termination	Completed		9/8/2003			
AFFECTED MEDIA & CONTAMINANTS:								
		Media:						
Contaminant:		Ground Water	Surface Water	Soil	Sediment	Air	Bedrock	
Petroleum Products-Unspecified				R				
		Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level S - Suspected R - Remediated RA - Remediated-Above RB - Remediated-Below						
USEPA SF  1419857								
Toxics Cleanup Program		Integrated Site Information System				Page 1 of 2		

CleanupSiteDetails2014